

Accentra Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
3-00-247237	Flue Tail Pipe		Y	\$ 16.39
1-10-247142P	Feeder Shield Right	Pre 008402885		\$ 51.30
1-10-247554		Post 008402885		\$ 55.10
1-10-247141P	Feeder Shield Left	Pre 008402885		\$ 41.80
1-10-247553		Post 008402885		\$ 45.60
1-10-247213A	Hopper Assembly	Pre 008400001		\$ 164.80
1-10-247778A		Post 008403501		\$ 225.00
3-20-232108	Hopper Switch 48"	Post 008403501	Y	\$ 34.99
2-00-247185L	Top Bolt Down Cover	Qty. 2 Req.		\$ 3.99
3-20-6866	Differential Switch		Y	\$ 17.60
2-00-247119B	Z Bracket, Right			\$ 10.00
2-00-247139B	Z Bracket, Left			\$ 10.00
3-40-247100	Glass Hopper Lid		Y	\$ 71.49
4-00-247236S	Cast Top			\$ 168.00
4-00-247106D	Cast Side Plate Left			\$ 160.00
2-00-247219B	Air Jacket Top			\$ 39.90
4-00-247104D	Cast Combustion Housing			\$ 112.20
1-10-247124W	Comb Intake Assembly			\$ 40.00
2-00-247126-1S	Comb Manifold Latch Left			\$ 6.00
4-00-247103D	Cast Heat Exchanger			\$ 196.50
3-00-247105	Cast Accordion Cover	Qty. 2 Req.		\$ 57.00
1-10-08736	Burn Pot Assembly		Y	\$ 113.19
3-20-677200	Ignitor		Y	\$ 91.49
2-00-06620B	Ignitor Cradle			\$ 3.99
2-00-06621B	Ignitor Holder		Y	\$ 9.99
2-00-06633L	Ignitor Flat Bottom			\$ 3.99
3-00-08534	Flame Guide		Y	\$ 24.49
	Door Latch Assembly			
2-00-247175L	Latch Bar			\$ 9.00
2-00-247187L	Dowel Pin Retainer			\$ 3.99
3-30-125200259	SH Shoulder Screw 5/16 x			\$ 6.00
3-30-92141	FW 18-8 5S			\$ 3.99
3-31-025125	Dowel Pin 1/4" x 1-1/4"			\$ 3.99
	Door Handle Assembly			
3-00-247112-4	Door Handle - Gold Plated			\$ 28.00
3-30-625202501	RPH MS 1/4-20 x 2-1/2			\$ 3.99
3-40-00247	Wooden Handle			\$ 6.00
1-10-247109A	Cast Door w/Rope and Grill			\$ 262.50
1-00-00888	Door Rope			\$ 26.00
3-00-247114	Cast Air Grill			\$ 22.00
3-40-247127	Door Glass		Y	\$ 44.29
1-00-2312	Glass Rope		Y	\$ 1.49 ft
2-00-247156B	Glass Retainer	Qty. 2 Req.		\$ 6.00
4-00-247108C	Cast Front Frame			\$ 121.60
1-10-247160	Ash Pan Weldment			\$ 58.90
2-00-247131-1B	Accordion Cover Latch - Left			\$ 15.00
2-00-247131-2B	Accordion Cover Latch - Right			\$ 15.00

Accentra Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
4-00-247110D	Cast Base Plate			\$ 195.20
2-00-247117S	Distribution Blower Plate			\$ 12.50
4-00-247113D	Cast Hinge	Qty. 2 Req.		\$ 22.00
4-00-247107D	Cast Side Plate Right			\$ 168.00
3-21-29045	Distribution Blower		Y	\$ 166.99
1-00-29045	Wire Kit (Needed for Bay Motor to EBM)			\$ 22.00
2-00-247126-2S	Combustion Manifold Latch, Right			\$ 6.00
1-10-247121S	Air Jacket BTM Weldment			\$ 93.60
3-21-08639	Combustion Blower		Y	\$ 108.99
3-20-40985	Fan Blade, Single Paddle 5" (Comb Blower)		Y	\$ 17.79
1-10-247677A	Feeder Assembly	Pre 008400001		\$ 421.40
1-10-247777A		Post 008400001		\$ 315.00
2-00-773850	Arrow Burn Pot Scraper			\$ 9.00
3-30-3125200252	Ball Spring Bracket Screw (BHSCS 1/4-20 X 1/4")			\$ 3.99
3-30-3125200381	BHSCS 1/4-20 x 3/8" (Glass Clip Screws)			\$ 3.99
3-44-00409	Burn Pot Gasket	Qty. 2 Req.	Y	\$ 4.99
3-43-02000-8	Brushed Nickel Knob			\$ 15.40
1-00-05886	Circuit Board		Y	\$ 148.99
3-31-605	Control Board Knob/D-Shaft	Qty. 3 Req.	Y	\$ 3.99
1-10-247157S	Control Board Plate Assembly			\$ 134.40
3-31-015	Dee Shaped Control Knob Shaft	Qty. 3 Req.	Y	\$ 3.99
3-44-247118	Distribution Blower Gasket			\$ 9.00
2-00-247173B	Distribution Blower Screen Frame	Pre 008402885		\$ 19.80
3-00-247112-4	Door Handle - Gold Plated			\$ 28.00
3-20-49447	Fuse 6 AMP			\$ 3.99
3-44-247300	Gasket,Glass Hopper Lid	Pre 11340		\$ 15.40
1-00-375501		Post 11340		\$ 96.90
3-43-02000	Gold Plated Knob (Hopper)			\$ 6.00
3-31-5500	Hopper Ball Spring Plunger (Threaded)			\$ 9.00
2-00-247116	Hopper Lid Ball Spring Mount Bracket	Pre 11340		\$ 3.99
1-10-247100	Hopper Lid Glass Assembly w/Gasket	Pre 11340		\$ 70.20
2-00-06694	Hopper Lid Hinge			\$ 24.00
2-00-247167	Hopper Lid Spring Latch	Pre 11340		\$ 3.99
1-00-247234	Inlet Reduction Ring (Combustion Blower)			\$ 47.50
3-31-95606	Nylon Washer 1/4" (Used with Screw Post - 4 per)			\$ 3.99
3-90-08326	Owners Manual			\$ -
3-44-06179	Pellet Tailpipe Gasket		Y	\$ 9.49
3-31-3614087	Pillow Block - 1/2"			\$ 6.00
3-20-39685	Power Cord - 8'			\$ 12.50
3-20-07625	Rocker Switch			\$ 6.00
3-20-00906	Room Sensor		Y	\$ 20.49
3-31-129004	Screw Post 1/4" (Hopper Lid - 2 per)			\$ 3.99
1-00-00744	Thermister Probe Replacement w/Gel Caps	Pre 00840167	Y	\$ 56.49
3-20-00844	Thermister Probe (ESP Probe)	Post 00840167	Y	\$ 41.99
3-20-00607	Thermostat Extension		Y	\$ 10.91
3-20-08727	Wiring Harness			\$ 47.50
	Wood Handle Bolt			

Accentra Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

Stocked
At
Squier
Lumber

SQUIER
LUMBER
2010
PRICING

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
Old Feeder				
1-10-247221W	Air Intake Weldment			\$ 20.66
1-10-677150	Feeder Weldment		Y	\$ 278.99
1-10-08037	Slide Plate Assembly		Y	\$ 32.99
1-10-247220	Pusher Arm Assembly			\$ 28.00
3-44-677153	Gasket, EPDM Feeder Cover			\$ 3.99
2-00-677152B	Feed Cover			\$ 9.00
3-20-08752	Gear Motor, 4 RPM		Y	\$ 96.49
1-10-677005	Bracket, Gear Motor			\$ 17.60
3-31-00075	Tensioner			\$ 6.00
3-50-08762	Small Sprocket W/ Hub			\$ 30.00
3-50-06667	56 Pin Chain			\$ 19.80
3-50-06626	Large Sprocket W/O Hub		Y	\$ 18.29
3-00-00153	Cast Cam Block			\$ 19.80
3-31-3014	Cam Bearing			\$ 12.50
2-00-04035L	Bearing Flange			\$ 6.00
3-50-00465	Auger Assembly		Y	\$ 80.49
1-10-06810A	Air Intake Damper Assembly			\$ 17.60
UL Feeder - Beginning Serial Number 008400001				
3-20-00677	Pellet Feeder Gear Motor, 4 RPM		Y	\$ 96.49
3-31-3014	UL Feeder Cam Bearing			\$ 12.50
1-00-511427	9MM Silicone Tube			\$ 39.90
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99
1-10-247239	UL Feeder Air Intake			\$ 32.00
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-724132	Ultra Feeder Weldment			\$ 95.40
1-10-677131W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-677155	Gasket, UL Feeder Cover			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40
3-50-00565	UL Feeder Auger Assembly		Y	\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00
3-00-677154	UL Feeder Cam Block			\$ 19.80