

Advance Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.
 Service or replacement parts for your appliance please provide model number and

Serial Numbers. Stock availability is determined by normal

**Stocked
At
Squier
Lumber**

**SQUIER
LUMBER
2010
PRICING**

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
3-20-6866	Differential Switch		Y	\$ 16.29
1-10-09731S	UL Hopper Assembly	Pre 008360001		\$ 241.50
1-10-06784A		008360001 Thru 008362435		\$ 238.50
1-10-09876A		Post 008362435		\$ 228.00
3-20-232108		Hopper Switch 48"	Post 008362469	Y
2-00-06617P	UL Feeder Hopper Rear Shield Left	Pre 008360001		\$ 51.30
2-00-06788B		Post 008360001		\$ 22.00
2-00-06616P	UL Feeder Hopper Rear Shield Right	Pre 008360001		\$ 53.20
2-00-06789B		Post 008360001		\$ 22.00
	Hopper Lid Assembly			
2-00-06696	Hopper Lid Latch			\$ 6.00
3-40-06693	Hopper Lid			\$ 43.70
3-43-02000	Hopper Knob	Gold		\$ 6.00
3-43-02000-8		Brushed Nickel		\$ 15.40
2-00-06694	Hinge			\$ 24.00
4-00-08739P	Top			\$ 188.80
3-43-03000-1	Tile Set	Cream		\$ 44.00
3-43-03000-2		Brown		\$ 44.00
3-43-03000-3		Black		\$ 44.00
3-43-03000-4		Green		\$ 44.00
1-00-05886	Circuit Board		Y	\$ 148.99
2-00-06610-1P	Side Door - Left			\$ 66.50
3-00-06644	Flame Guide		Y	\$ 24.49
1-10-00675	Burn Pot		Y	\$ 113.19
3-20-677200	Burn Pot Ignitor		Y	\$ 91.49
2-00-06620B	Ignitor Cradle			\$ 3.99
2-00-06621B	Ignitor Holder		Y	\$ 9.99
2-00-06633L	Ignitor Flat Bottom			\$ 3.99
3-43-06642-4	Grill Weldment	Gold		\$ 125.80
3-43-06642-8		Brushed Nickel		\$ 112.20
3-43-06613-4	Frame	Gold		\$ 208.50
3-43-06613-8		Brushed Nickel		\$ 228.00
1-10-07581A	Ash Pan Weldment			\$ 95.00
1-10-08612A	Door Assembly			\$ 359.80
3-40-08728	Large Front Glass		Y	\$ 74.55
3-40-08729	Side Glass		Y	\$ 26.45
1-00-11862	Glass Gasket		Y	\$ 1.29 ft
1-10-08553S	Retainer Assembly			\$ 19.80
1-10-07574W	Combustion Intake Weldment			\$ 26.00
2-00-06610-2P	Side Door - Right			\$ 70.20
3-21-22647	Distribution Blower		Y	\$ 142.99
3-21-08639	Combustion Blower		Y	\$ 108.99
2-00-06612B	Hopper Heat Shield Rev - A			\$ 34.00
3-44-06179	Pellet Tailpipe Gasket		Y	\$ 9.49

Advance Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.
 Service or replacement parts for your appliance please provide model number and

items. Stock availability is determined by normal

**Stocked
At
Squier
Lumber**

**SQUIER
LUMBER
2010
PRICING**

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
3-00-247237	Pellet Tailpipe Cast Kit A		Y	\$ 16.39
2-00-06770P	Latch Adjuster			\$ 10.00
2-00-06771P	Spring Holder			\$ 3.99
3-30-1252007513	HCS 1/4-20 x 3/4" Z 5	Qty. 2 Req.		\$ 3.99
3-30-1252008713	HCS 1/4-20 x 7/8" Z 5			\$ 3.99
3-50-00058	Bushing 3/8 OD x 1/4 OAL			\$ 6.00
3-50-08288	Latch Bushing 3/8 OD x 5/16 OAL			\$ 3.99
3-30-80252013	FHN 1/4-20 Z5	Qty. 3 Req.		\$ 3.99
1-10-08735W	Door Hinge Weldment	Qty. 2 Req.		\$ 12.50
3-31-00927	Spring Latch	Qty. 2 Req.		\$ 12.50
Old Feeder				
1-10-06593W	Air Intake Weldment			\$ 36.00
1-10-677150	Feeder Weldment		Y	\$ 278.99
1-10-08037	Slide Plate Assembly		Y	\$ 32.99
1-10-01530	Pusher Arm Assembly			\$ 28.00
3-44-677153	Gasket, EPDM Feeder Cover			\$ 3.99
2-00-677152B	Feed Cover			\$ 9.00
3-20-08752	Gear Motor, 4 RPM		Y	\$ 96.49
1-10-677005	Bracket, Gear Motor			\$ 17.60
3-31-00075	Tensioner			\$ 6.00
3-50-08550	Large Sprocket With hub		Y	\$ 24.49
3-50-06667	Drive Chain 60 Pin			\$ 19.80
3-50-06626	Large Sprocket Without hub			\$ 19.80
3-00-00153	Cast Cam Block			\$ 19.80
3-31-3014	Cam Bearing			\$ 12.50
2-00-04035L	Bearing Flange			\$ 6.00
3-50-00465	Auger Assembly		Y	\$ 80.49
1-10-06810A	Air Intake Damper Assembly			\$ 17.60
UL Feeder - Beginning Serial Number 0083600001				
3-20-00677	Pellet Feeder Gear Motor, 4 RPM		Y	\$ 96.49
3-31-3014	UL Feeder Cam Bearing			\$ 12.50
1-00-511427	9MM Silicone Tube			\$ 39.90
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99
1-10-677183	UL Feeder Air Intake			\$ 43.70
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-724132	Ultra Feeder Weldment			\$ 95.40
1-10-677131W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-677155	Gasket, UL Feeder Cover			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40
3-50-00565	UL Feeder Auger Assembly		Y	\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00

Advance Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.
Service or replacement parts for your appliance please provide model number and
items. Stock availability is determined by normal

Stocked
At
Squier
Lumber

SQUIER
LUMBER
2010
PRICING

PART NUMBER	Description	COMMENTS		
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00
3-00-677154	UL Feeder Cam Block			\$ 19.80