

Hydroflex 60

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked at Squier Lumber	Squier Lumber 2010 PRICING
1-10-232044	Plumbing Support Kit - Qty. 2 req.			\$ 19.80
1-10-232060A	Firetube Cleanout Door Assembly			\$ 252.00
3-40-232054	Draft Section Refractory Side	Qty. 2 req.		\$ 60.80
3-31-782124	1/4-20 x 1-1/2" Wingscrew with Collar	Qty. 3 req.		\$ 3.99
1-10-232011W	Draft Section Weldment			\$ 217.20
3-44-232089	1/2" Foam Insulation Wrap Around			\$ 88.20
3-44-232088	1/2" Foam Insulation			\$ 66.60
1-10-232034A	Hopper Assembly			\$ 317.80
2-00-232039B	Feeder Shield Rear			\$ 53.20
3-44-232085	1" Foil Faced Fiberglass Insulation			\$ 15.40
1-10-232108A	UL Feeder Assembly			\$ 345.80
3-44-677185A	Airwash Pipe Gasket			\$ 3.99
3-20-6866	Differential Switch		Y	\$ 16.29
3-20-00450	Tempco 450W Igniter			\$ 132.80
3-44-677185	UL Feeder to Hopper Gasket			\$ 19.80
3-44-232086	1" Foil Faced Fiberglass Insulation			\$ 15.00
2-00-232008B	Tube Cleanout Plate	Qty. 2 req.		\$ 36.00
2-00-232031-1B	Hopper Stiffner Bracket Left			\$ 15.00
2-00-232031-2B	Hopper Stiffner Bracket Right			\$ 15.00
3-40-232010	Firebox Refractory Side	Qty. 2 req.		\$ 64.80
3-99-7498	Burn Pot Scraper			\$ 24.00
3-44-232094-1	Combustion Section Gasket			\$ 3.99
3-44-232094-2	Long Bottom Gasket			\$ 9.00
3-44-232094-3	Short Bottom Gasket			\$ 9.00
3-20-02679	Air Pump			\$ 193.50
3-20-02679A	Filter			\$ 3.99
3-20-02679B	Fitting			\$ 3.99
3-44-232078	1/4" Ceramic Paper Feeder Insulation			\$ 32.00
3-10-00600	3/4" NPT Square Plug	Qty. 4 req.		\$ 3.99
2-00-232096B	Feeder Cover Left			\$ 43.70
3-10-07560	3/4" NPT Boiler Drain			\$ 24.00
2-00-232026B	Outer Skin Left			\$ 86.40
1-10-232005W	Combustion Section Weldment			\$ 262.50
3-50-05229	Steel Sleeve Bushing 3/8 OD x 1/2 OAL			\$ 3.99
3-30-937161501	Elevator Bolt 3/8-16 x 1-1/2"	Qty. 4 req.		\$ 3.99
2-00-232056B	Firebox Cleanout Cover Retainer	Qty. 2 req.		\$ 15.00
2-00-232052B	Tube Cleanout Cover Plate	Qty. 2 req.		\$ 36.00
3-20-1000	3/8" Flex Connector	Qty. 2 req.		\$ 6.00
3-20-05238	Ceramic Insert			\$ 3.99
3-00-03000	Flame Guide		Y	\$ 24.49
1-10-232079A	Burnpot Assembly			\$ 112.20
3-44-724114	Ceramic Insert Gasket			\$ 22.00
2-00-724104	Ceramic Insert Plate			\$ 24.00
3-44-724115	Burn Pot Gasket			\$ 22.00
3-40-232015	Firebox Refractory Rear			\$ 81.00
3-40-232093	Firebrick			\$ 57.00

Hydroflex 60

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked at Squier Lumber	Squier Lumber 2010 PRICING
3-40-232006	Firebox Refractory Bottom			\$ 49.40
1-10-232049A	Ash Pan Assembly			\$ 88.20
1-10-232019A	Ash Door Assembly			\$ 313.60
1-10-232055A	Control Board Assembly			\$ 262.50
1-00-06143	Board Only			\$ 166.40
3-10-78427	Pressure / Temperature Gauge			\$ 86.40
1-10-232080A	Plumbing Assembly			\$ 132.80
2-00-232028B	Combustion Motor Cover			\$ 39.90
2-00-232027B	Outer Skin Front			\$ 90.00
3-21-08639	Draft Blower		Y	\$ 108.99
3-20-502221	Blade 5" Single		Y	\$ 13.99
3-31-004357	External Retaining Ring			\$ 3.99
2-00-232071B	Flex Conduit Support Bracket			\$ 19.80
1-00-25043	3/8" Flex Conduit			\$ 22.00
2-00-232020L	Ash Door Hinge			\$ 12.50
1-10-232001W	Water Jacket Weldment			\$ 781.30
2-00-232053S	Spiral Fire Tube Baffle	Qty. 14 req.		\$ 17.60
3-20-00844	ESP Probe		Y	\$ 41.99
3-44-232087	1/2" Foam Insulation			\$ 41.80
3-44-232090	2" Fiberglass Insulation	Qty. 2 req.		\$ 17.60
2-00-232097B	Feeder Cover Right			\$ 43.70
2-00-232025B	Outer Skin Right			\$ 88.20
3-31-00927	Spring Latch	Qty. 4 req.		\$ 12.50
3-30-2937160252	SSS CP 3/8-16 x 1/4" (draft plug)			\$ 3.99
UL Feeder				
3-20-09302	Pellet Feeder Gear Motor, 6RPM		Y	\$ 164.99
3-31-3014	UL Feeder Cam			\$ 12.50
1-00-511427	9MM Silicone Tube		Y	\$ 4.89 ft
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99
1-10-72222	UL Feeder Air Intake			\$ 30.00
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-677187W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-677155	Gasket, UL Feeder Cover			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40
3-50-00565	UL Feeder Auger Assembly		Y	\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00
3-00-677154	UL Feeder Cam Block			\$ 19.80