

Oakwood Cast Iron Wood Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

Stocked At Squier Lumber

SQUIER LUMBER 2010 PRICING

| PART NUMBER | Description | COMMENTS | Stocked At Squier Lumber | SQUIER LUMBER 2010 PRICING |
|-----------------|-------------------------------|-------------|--------------------------|----------------------------|
| 2-00-249162S | UL Label Outer Shield | | | \$ 17.60 |
| 2-00-249161S | UL Label Inner Shield | | | \$ 12.50 |
| 1-10-249116A | Rear Housing Cover Assembly | | | \$ 115.60 |
| 1-10-249109 | Flue Collar Cover with Gasket | | | \$ 12.50 |
| 4-00-249110S | Rear Housing | | | \$ 190.50 |
| 1-00-08121 | Cook Grill Assembly | Optional | | \$ 44.00 |
| 4-00-249108D | Flue Collar | | | \$ 73.80 |
| 2-00-249147S | Top Hinge Plate | Qty. 2 Req. | | \$ 9.00 |
| 4-00-249105P | Top | | | \$ 196.80 |
| 3-00-249115P | Top Load Door | | | \$ 108.80 |
| 2-00-249148 | Top Load Handle | | | \$ 15.00 |
| 4-00-249103D | Left Side Panel | | | \$ 107.10 |
| 4-00-249111S | Inner Front | | | \$ 179.20 |
| 3-00-249101P | Andiron | Qty. 2 Req. | | \$ 15.40 |
| 4-00-249112P | Front Load Door | | | \$ 184.00 |
| 3-40-00123 | Wooden Handle | Qty. 2 Req. | | \$ 9.00 |
| 3-00-249121P | Ash Lip | | | \$ 62.70 |
| 2-00-249169L | Ash Fender Bolt Plate | Qty. 2 Req. | | \$ 9.00 |
| 3-40-08746 | Wood Knob | | | \$ 6.00 |
| 4-00-249113D | Ash Door | | | \$ 53.20 |
| 2-00-249188L | Hinge Stiffener | | | \$ 9.00 |
| 1-10-249151 | Ash Pan | | | \$ 41.80 |
| 1-10-249144S | Steel Ash Box Weldment | | | \$ 171.20 |
| 2-00-249157B | Ca Shield | | | \$ 15.40 |
| 4-00-249100P | Leg | Qty. 4 Req. | | \$ 30.00 |
| 4-00-249104D | Bottom | | | \$ 237.00 |
| 4-00-249102D | Right Side Panel | | | \$ 107.10 |
| 1-10-249106 | Damper Frame Assembly | | | \$ 172.80 |
| 4-00-249107D | Damper | | | \$ 62.70 |
| | Air Slide Assembly | | | |
| 2-00-249158S | Air Adjuster Pipe | Qty. 2 Req. | | \$ 12.50 |
| 1-10-249130S | Air Adjuster Weldment | | | \$ 22.00 |
| 1-10-249131W | AirSlide Weldment | | | \$ 17.60 |
| 2-00-249190 | Top Handle Retainer | | | \$ 3.99 |
| Hardware | | | | |
| 3-30-02003113 | SAE FW 5/16" Z | Qty. 6 Req. | | \$ 3.99 |
| 3-30-02002514 | USS FW 1/4" Z | Qty. 3 Req. | | \$ 3.99 |
| 3-30-0400311 | Washer .3125 D | Qty. 2 Req. | | \$ 9.00 |
| 3-50-00058 | Bushing 3/8 OD X 1/4" OAL | Qty. 2 Req. | | \$ 6.00 |
| 3-30-3025201002 | SHCS 1/4-20 x 1" | | | \$ 3.99 |
| 3-30-80252013 | FHN 1/4-20 Z5 | Qty. 2 Req. | | \$ 3.99 |
| 3-30-3125200381 | BHSCS 1/4-20 x 3/8" | 20 per | | \$ 3.99 |
| 3-30-2931180382 | SSS CP 5/16-18 x 3/8" | Qty. 2 Req. | | \$ 3.99 |
| 3-30-431182001 | CB 5/16-18 x 2 Z (legs) | Qty. 4 Req. | | \$ 3.99 |
| 3-40-06999 | Combustion Paackage | | | \$ 253.50 |
| 3-40-00104 | Inlet Brick Right | | | \$ 79.20 |

Oakwood Cast Iron Wood Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

**Stocked
At
Squier
Lumber**

**SQUIER
LUMBER
2010
PRICING**

| PART NUMBER | Description | COMMENTS | | |
|--------------|----------------------------------|-------------|--|----------|
| 3-40-00101 | Logo Brick | | | \$ 60.80 |
| 3-40-00103 | Inlet Brick Left | | | \$ 95.40 |
| 2-00-249172B | Upper Brick Clip | Qty. 2 Req. | | \$ 9.00 |
| 2-00-249153 | Rear Brick Clip | Qty. 2 Req. | | \$ 10.00 |
| 1-10-249117A | Cast Left Inside Plate | | | \$ 40.00 |
| 2-00-249122 | Grate | | | \$ 32.00 |
| 1-10-249118A | Cast Right Inside Plate | | | \$ 40.00 |
| 2-00-249135 | Rear Brick Retainer | Qty. 2 Req. | | \$ 3.99 |
| 3-40-00100 | Shoe Brick | | | \$ 90.00 |
| 3-40-00102 | Side Brick | Qty. 2 Req. | | \$ 79.20 |
| 1-00-02492 | Back Heat Shield Kit -Top Vent | | | \$ 56.00 |
| 1-00-02493 | Back Heat Shield Kit - Rear Vent | | | \$ 51.00 |
| 1-00-02494 | Outside Air Option | | | \$ 27.00 |
| 1-00-02491 | Bottom Heat Shield Kit | | | \$ 45.00 |