

P61A Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y-

These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

Stocked
at
Squier
Lumber

SQUIER
LUMBER
2010
PRICING

PART NUMBER	Description	COMMENTS		
1-10-08622	Hopper Assembly	Pre 008085803		\$ 216.00
1-10-06819A		008085803 Thru 008087704		\$ 198.00
3-20-232108	Hopper Switch 48"	Post 008087704	Y	\$ 34.99
1-10-09674A	Feeder Assembly	Pre 008085803		\$ 397.60
1-10-09684A		Post 008085803		\$ 347.20
3-00-247237	Flue Tail Pipe		Y	\$ 16.39
2-00-06470P	Auger Motor Cover			\$ 28.00
2-00-06467P	Auger Motor Shield			\$ 24.00
3-20-6866	Differential Switch		Y	\$ 16.29
3-21-22647	Distribution Blower		Y	\$ 142.99
3-21-08639	Combustion Motor		Y	\$ 108.99
2-00-06468-1P	Rear Cover Left			\$ 22.00
2-00-06468-2P	Rear Cover Right			\$ 22.00
1-10-08516S	Comb Intake Weldment			\$ 22.00
1-10-08533S	Retainer Assembly			\$ 15.00
1-10-05800	Ash Pan			\$ 62.70
1-10-06724S	Ash Door Assembly			\$ 96.90
2-00-06952B	Bolt on Hinge			\$ 10.00
4-00-06800P	Cast Door Frame			\$ 97.20
3-40-950133125	Glass Panel		Y	\$ 56.49
1-00-08704	Door Handle Assembly	Pre 13546	Y	\$ 40.49
1-00-453001		Post 13546		\$ 55.10
	Contains: Wooden Handle, Wave Washer, SHCS, Cast Handle, , SSS, Bhcs, Cast Pawl			
3-40-00247	Wooden Handle, Load Door			\$ 6.00
1-10-05802	Burn Pot Weldment		Y	\$ 113.19
3-00-08534	Flame Guide		Y	\$ 24.49
2-00-06623	Clean Out Cover			\$ 6.00
3-31-782108	Thumb Screw	Qty 2 req		\$ 3.99
3-40-900450125	Fire Brick 4-1/2 x 9 x 1-1/4"	Qty 3 req		\$ 6.00
2-00-06471B	Hopper Heat Shield			\$ 24.00
2-00-773826L	Feeder Cover			\$ 6.00
1-00-05886	Circuit Board		Y	\$ 148.99
1-10-08327	Circuit Board Plate			\$ 26.00
3-31-605	Knob, Contol Board/D-Shaft	Qty 3 req	Y	\$ 3.99
3-31-015	Control Knob Shaft, D-Shaped	Qty 3 req	Y	\$ 3.99
Accessories				
2-00-773850	Arrow Burn Pot Scraper			\$ 9.00
	Cradle Assembly			
2-00-06621B	Igniter Holder			\$ 10.00
2-00-06620B	Igniter Cradle			\$ 3.99
2-00-06633L	Igniter Flat Bottom			\$ 3.99
3-20-502221	Fan Blade, 5" Double Paddle (Combustion Blower)		Y	\$ 15.29
3-20-49447	Fuse, 6 Amp			\$ 3.99

P61A Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y-

These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

Stocked
at
Squier
Lumber

SQUIER
LUMBER
2010
PRICING

PART NUMBER	Description	COMMENTS	Stocked at Squier Lumber	SQUIER LUMBER 2010 PRICING
1-00-2312	Gasket, 1/4" Rope Black W/PSA Per Inch (Glass)		Y	\$ 1.49 ft
1-00-00888	Gasket, 3/8" Rope White LD Per Inch (Ash or Load Door)			\$ 26.00
3-44-00409	Gasket, Burn Pot		Y	\$ 3.99
1-00-00248	Gasket, Hopper			\$ 22.00
3-44-677185	Gasket, Hopper Throat			\$ 19.80
3-44-06179	Gasket, Pellet Tailpipe			\$ 9.00
2-00-773862	Glass Clip	Qty 4 req		\$ 3.99
1-10-09109	Hopper Lid W/Hinge			\$ 60.80
3-20-677200	Igniter		Y	\$ 91.49
3-31-199110	Latch, Swell/Hopper			\$ 12.50
3-40-6618	Muffler		Y	\$ 15.00
3-40-1818	Muffler Fitting		Y	\$ 10.00
1-10-08542	Outside Air Vent		Y	\$ 53.00
3-20-00906	Room Sensor		Y	\$ 20.49
3-20-00607	Thermostat Extension			\$ 15.00
1-00-00744	Thermister Probe (ESP Probe)	Pre 008085803	Y	\$ 56.49
3-20-00844		Post 008085803	Y	\$ 49.40
3-20-08727	Wiring Harness			\$ 47.50
3-90-05822	Owners Manual			\$ -
3-42-1990	Touch Up Spray Paint (12 ounce)	Black	Y	\$ 11.99
3-42-6196		Metalic blue	Y	\$ 11.99
3-42-6198		Forest Green	Y	\$ 11.99
3-42-6201		Charcoal	Y	\$ 11.99
3-42-6319		Mojave Red	Y	\$ 11.99
Old Feeder				
1-10-06810A	Air Intake Damper Assembly			\$ 17.60
1-10-06461	Air Intake Weldment			\$ 30.00
1-10-677150	Feeder Weldment		Y	\$ 278.99
1-10-08037	Slide Plate Assembly		Y	\$ 32.99
1-10-06691	Pusher Arm Assembly			\$ 32.00
3-44-677153	Gasket, EPDM Feeder Cover			\$ 3.99
2-00-677152B	Feed Cover			\$ 9.00
3-50-00465	Auger Assembly		Y	\$ 80.49
3-31-3014	Cam Bearing			\$ 12.50
2-00-04035L	Bearing Flange			\$ 6.00
2-00-01534L	Bracket, Gear Motor			\$ 3.99
3-20-60906	Gear Motor, 4 RPM		Y	\$ 111.99
3-00-00153	Cast Cam Block			\$ 19.80
UL Feeder - Beginning Serial Number 008085092				
3-20-60906	Pellet Feeder Gear Motor, 4RPM		Y	\$ 111.99
3-31-3014	UL Feeder Cam			\$ 12.50
1-00-511427	9MM Silicone Tube		Y	\$ 39.90
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99

P61A Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number. (Y-

These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

Stocked
at
Squier
Lumber

SQUIER
LUMBER
2010
PRICING

PART NUMBER	Description	COMMENTS		
1-10-72222	UL Feeder Air Intake			\$ 30.00
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-724132	Ultra Feeder Weldment			\$ 95.40
1-10-677131W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-677155	Gasket, UL Feeder Cover			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40
3-50-00565	UL Feeder Auger Assembly		Y	\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00
3-00-677154	UL Feeder Cam Block			\$ 19.80