

PB105 Pellet Boiler

IMPORTANT: THIS IS DATED INFORMATION.
 Service or replacement parts for your appliance please provide model number and
 items. Stock availability is determined by normal

**Stocked
at Squier
Lumber**

**Squier
Lumber
2010
PRICING**

| PART NUMBER | Description | COMMENTS | Stocked at Squier Lumber | Squier Lumber 2010 PRICING |
|--------------|---------------------------------|----------------|--------------------------------|-------------------------------------|
| 2-00-72174B | Jacket Backside | | | \$ 66.50 |
| 3-44-72178 | Water Jacket Insulation Back | | | \$ 47.50 |
| 2-00-72172B | Jacket Top | | | \$ 62.70 |
| 3-44-72179 | Water Jacket Insulation Top | | | \$ 53.20 |
| 2-00-72170B | Jacket Top Angle | | | \$ 12.50 |
| 3-44-72176 | Water Jacket Insulation Left | | | \$ 55.10 |
| 3-44-35263 | Flame Guide Insulator | | | \$ 60.80 |
| 3-20-05238 | Ceramic Insert | | | \$ 3.99 |
| 3-44-724115 | Burn Pot Gasket | | | \$ 22.00 |
| 3-20-677200 | Tempco 450W Ignitor | Pre 008341121 | Y | \$ 91.49 |
| 3-20-00450 | | Post 008341121 | | \$ 132.80 |
| 3-20-02679 | Air Pump | | | \$ 193.50 |
| 3-20-02679A | Air Pump Filter | | | \$ 3.99 |
| 3-20-02679B | Air Pump Fitting | Post 008341121 | | \$ 3.99 |
| 3-20-02679C | Feet | | | \$ 3.99 |
| 2-00-853500B | Bracket | | | \$ 17.60 |
| 1-10-72140A | Hopper Assembly | | | \$ 299.60 |
| 1-10-07330 | Control Board Plate | | | \$ 40.00 |
| 1-00-06143 | Control Board | | Y | \$ 149.99 |
| 2-00-72158B | Feeder Cover Assembly | | | \$ 102.00 |
| 3-20-6866 | Differential Switch | | Y | \$ 16.29 |
| 3-31-72196 | Red Nylon Knob | | | \$ 15.00 |
| 1-10-72153A | Swing Plate Assembly | | | \$ 192.00 |
| 2-00-724104 | Ceramic Insert Plate | | | \$ 24.00 |
| 3-44-724114 | Ceramic Insert Gasket | | | \$ 22.00 |
| 1-10-73403 | Burn Pot | | Y | \$ 153.99 |
| 3-00-08534 | Flame Guide | | Y | \$ 22.49 |
| 2-00-72173B | Jacket Side Front | | | \$ 64.60 |
| 3-44-72175 | Water Jacket Insulation Front | | | \$ 55.10 |
| 1-10-72120S | View Door Assembly | | | \$ 126.00 |
| 1-10-72121A | Mounting Plate Assembly | | | \$ 163.20 |
| 1-00-88100 | View Door Mounting Plate Gasket | | | \$ 26.00 |
| 1-89-07205W | Finished Body Weldment | | | \$ 2,190.50 |
| 2-00-01036 | Cleanout Rod | Qty. 3 Req. | | \$ 22.00 |
| 3-20-52171 | 4 x 4 Steel Box | | | \$ 10.00 |
| 3-10-05060 | 3/4" NPT Boiler Drain | Pre 008341121 | | \$ 40.00 |
| 3-10-07560 | | Post 008341121 | | \$ 24.00 |
| 2-00-72171B | Jacket Side Right | | | \$ 53.20 |
| 3-44-72177 | Water Jacket Insulation Right | | | \$ 51.30 |
| | Boiler Kit | | | |
| 3-10-78422 | Press Temp Guage Bottom Mount | | | \$ 64.80 |
| 3-10-935111 | Immersion Well Wel11A-601R | | | \$ 102.00 |
| 3-10-77382 | Pressure Relief | | | \$ 24.00 |
| | Water Plate Kit | | | |
| 3-10-24758 | Water Plate Gasket | | | \$ 22.00 |

PB105 Pellet Boiler

IMPORTANT: THIS IS DATED INFORMATION.
 Service or replacement parts for your appliance please provide model number and

items. Stock availability is determined by normal

**Stocked
at Squier
Lumber**

**Squier
Lumber
2010
PRICING**

| PART NUMBER | Description | COMMENTS | Stocked at Squier Lumber | Squier Lumber 2010 PRICING |
|---------------------|--|-----------------|--------------------------------|-------------------------------------|
| 2-00-01076L | Steel Water Plate | | | \$ 26.00 |
| 3-30-80431414 | 3-30-80431414 FHN | Qty. 6 Req. | | \$ 3.99 |
| | Handle Kit | | | |
| 3-40-00086-3 | Spring Handle .500 Dia | Qty. 3 Req. | | \$ 9.00 |
| 3-50-72189 | Scraper Rod Guide | Qty. 3 Req. | | \$ 6.00 |
| | Hardware Package | | | |
| 3-30-80311824 | FHN .3125-18 Z 8 Plain Nuts | Qty. 4 Req. | | \$ 3.99 |
| 3-30-03031 | External Tooth Lock Washer .3125 | Qty. 4 Req. | | \$ 3.99 |
| 3-30-131180509 | Shoulder Screw .3125 x 50 | Qty. 2 Req. | | \$ 6.00 |
| 3-30-8625203 | Nylon Lock Nut | Qty. 2 Req. | | \$ 3.99 |
| 1-00-00248 | Rubber Grommet (Hopper Lid) | | | \$ 22.00 |
| 1-00-88100 | 1" White Gasket w/PSA Single Ply | Access Plate | | \$ 26.00 |
| 1-00-88100 | | FDR Swing Plate | | \$ 26.00 |
| 1-00-88250 | 1" White Gasket w/PSA Double Ply | Firebox Door | | \$ 100.30 |
| 1-00-88250 | | Flue | | \$ 100.30 |
| Ash Pan Base | | | | |
| 1-00-88250 | Ash Base Gasket | | | \$ 100.30 |
| 3-44-72182 | Ash Chamber Insul Left Side | | | \$ 32.00 |
| 2-00-72125B | Ash Chamber Jacket Left with Relief Hole | | | \$ 20.00 |
| 1-10-72204 | Relief Door Assembly | | | \$ 40.00 |
| 2-00-72203B | Sheet Metal Bracket | Qty. 2 Req. | | \$ 24.00 |
| 1-10-72129 | Ash Pan Assembly | | | \$ 66.50 |
| 1-10-72137A | Ash Door Assembly | | | \$ 158.40 |
| 2-00-72132 | Access Plate w/Gasket | | | \$ 41.80 |
| 3-44-72207 | Access Plate Gasket only | | | \$ 20.00 |
| 1-10-00250W | Base Weldment | | | \$ 301.00 |
| 2-00-72126B | Ash Chamber Jacket Right, Left of Comb Hole | | | \$ 38.00 |
| 1-10-72145W | Flue Tunnel Weldment | | | \$ 156.80 |
| 3-21-08639 | Comb Blower | | Y | \$ 108.99 |
| 2-00-72158B | Feeder Cover | | | \$ 102.00 |
| 3-20-00844 | ESP Probe | | Y | \$ 41.99 |
| 2-00-72127B | Ash Chamber Jacket Right, Right of Comb Hole | | | \$ 38.00 |
| 3-44-72208 | Combustion Housing Gasket | | | \$ 12.50 |
| 3-44-72183 | Ash Chamber Insul Right Side | | | \$ 32.00 |
| 3-44-72184 | Ash Chamber Insul Back Side | | | \$ 26.00 |
| 2-00-72124B | Ash Chamber Jacket Back | | | \$ 41.80 |
| 1-10-73416 | Blower Mount - Mounting Bracket | | | \$ 20.00 |
| 3-20-502221 | 5" Double Blade | | Y | \$ 13.99 |
| 3-30-38125 | Door Pin Kit - Steel RH River .375 x 1-3/8" | Qty. 2 Req. | | \$ 3.99 |
| | Door Latch Kit | | | |
| 2-00-00036 | Door Latch | | | \$ 6.00 |
| 3-30-80312414 | FH Nut | | | \$ 3.99 |
| 3-30-3131240752 | BHSCS 5/16"-24 x 3/4" | | | \$ 3.99 |
| | Package | | | |
| 3-31-782108 | 1/4-20 Wing Screw with Collar | Qty. 4 Req. | | \$ 3.99 |

PB105 Pellet Boiler

IMPORTANT: THIS IS DATED INFORMATION.
 Service or replacement parts for your appliance please provide model number and
 items. Stock availability is determined by normal

**Stocked
at Squier
Lumber**

**Squier
Lumber
2010
PRICING**

| PART NUMBER | Description | COMMENTS | Stocked at Squier Lumber | Squier Lumber 2010 PRICING |
|------------------|---------------------------------------|-------------|--------------------------------|-------------------------------------|
| 3-30-80252013 | FHN 1/4-20 Z5 | Qty. 8 Req. | | \$ 3.99 |
| 3-31-782124 | 1/4-20 x 1-1/2" Wingscrew with Collar | Qty. 3 Req. | | \$ 3.99 |
| 3-30-511007517 | TEK Screw #10 3/4" | Qty. 8 Req. | | \$ 3.99 |
| 3-30-01002514 | USS LW .250 | Qty. 4 Req. | | \$ 3.99 |
| 3-30-510805016 | HWH TEKS 8 x 1/2" | Qty. 6 Req. | | \$ 3.99 |
| 3-30-1252010013 | HCS .25 x 1 Z 5 | Qty. 4 Req. | | \$ 3.99 |
| UL Feeder | | | | |
| 3-20-02524 | Pellet Feeder Gear Motor, 10RPM | | Y | \$ 129.99 |
| 3-31-3014 | UL Feeder Cam | | | \$ 12.50 |
| 1-00-511427 | 9MM Silicone Tube | | Y | \$ 39.90 |
| 1-10-06810A | Pellet Air Intake Assembly | | | \$ 178.60 |
| 3-44-72224 | Gasket Feeder Air Intake | | | \$ 3.99 |
| 1-10-72222 | UL Feeder Air Intake | | | \$ 30.00 |
| 3-44-677160 | Gasket Ultra Air Intake | | | \$ 3.99 |
| 1-10-724132 | Ultra Feeder Weldment | | | \$ 95.40 |
| 1-10-677187W | UL Feeder Pusher Arm | | | \$ 30.00 |
| 2-00-677138B | Fines Deflector | | | \$ 6.00 |
| 3-44-677155 | Gasket, UL Feeder Cover | | | \$ 3.99 |
| 2-00-677122L | UL Feeder Cover Short | | | \$ 6.00 |
| 1-10-677121A | Slide Plate Assembly | | | \$ 15.40 |
| 3-50-00565 | UL Feeder Auger Assembly | | Y | \$ 86.40 |
| 2-00-04035L | Pellet Feeder Bearing Retainer | | | \$ 6.00 |
| 2-00-247406L | UL Feeder Gear Motor Bracket | | | \$ 6.00 |
| 3-00-677154 | UL Feeder Cam Block | | | \$ 19.80 |