

PC-45 Corn Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

**Stocked
At
Squier
Lumber**

**SQUIER
LUMBER
2010
PRICING**

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
1-10-08622	Hopper Assembly			\$ 216.00
1-10-724129A	Feeder Assembly			\$ 387.80
3-00-247237	Flue Tail Pipe			\$ 24.00
2-00-02676P	Auger Motor Cover			\$ 28.00
2-00-06467P	Auger Motor Shield			\$ 24.00
3-20-6866	Differential Switch		Y	\$ 16.29
3-21-22647	Distribution Blower		Y	\$ 142.99
3-21-08639	Combustion Blower		Y	\$ 108.99
2-00-06468-1P	Rear Cover Left			\$ 22.00
2-00-06468-2P	Rear Cover Right			\$ 22.00
1-10-02677W	Combustion Intake Weldment			\$ 22.00
1-10-08533S	Retainer Assembly			\$ 15.00
1-10-05800	Ash Pan			\$ 62.70
1-10-06724S	Ash Door Assembly			\$ 96.90
2-00-06952B	Bolt on Hinge Weldment			\$ 10.00
4-00-06800P	Cast Door Frame			\$ 97.20
3-40-950133125	Glass Panel		Y	\$ 56.49
1-00-08704	Door Handle Assembly	Pre 1529		\$ 40.00
1-00-453001		Post 1529		\$ 55.10
3-40-00247	Wooden Handle, Load Door			\$ 6.00
	Burn Pot			
1-10-724108	Burn Pot Grate Weldment	Large Hole		\$ 43.70
1-10-724208		Small Hole		\$ 49.40
1-10-724103	Burn Pot Housing Weldment			\$ 55.10
3-00-02676	Auger Extension			\$ 36.00
2-00-724107	Burn Pot Front Plate			\$ 10.00
2-00-724105	Burn Pot Front Plate Lock			\$ 10.00
3-40-900450125	Fire Brick 4-1/2 x 9 x 1-1/4"	Qty 3 req		\$ 6.00
2-00-06471B	Hopper Heat Shield			\$ 24.00
2-00-773826L	Feeder Cover			\$ 6.00
1-00-05887	Circuit Board			\$ 166.40
1-10-02678	Circuit Board Plate			\$ 26.00
3-31-605	Knob, Control Board/D-Shaft	Qty 3 req	Y	\$ 3.99
3-31-015	Control Knob Shaft, D-Shaped	Qty 3 req	Y	\$ 3.99
	Gasket Placement			
3-44-00409	Gasket, Pellet Burn Pot		Y	\$ 4.99
3-44-724114	Gasket, Ceramic Insert Plate			\$ 22.00
2-00-724104	Insert Plate, Ceramic			\$ 24.00
3-20-05238	Insert, Ceramic			\$ 3.99
3-44-724115	Gasket, Burn Pot			\$ 22.00
Accessories				
3-20-02679	Air Pump			\$ 193.50
3-20-02679A	Air Pump Filter			\$ 3.99
3-20-02679B	Air Pump Fitting			\$ 3.99
1-00-724135	Air Pump Rebuild Kit			\$ 32.00
2-00-773850	Arrow Burn Pot Scraper			\$ 9.00
3-20-40985	Fan Blade, 5" Single Paddle (Combustion Blower)		Y	\$ 15.40

PC-45 Corn Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

**Stocked
At
Squier
Lumber**

**SQUIER
LUMBER
2010
PRICING**

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
3-20-49447	Fuse, 6 Amp			\$ 3.99
1-00-2312	Gasket, 1/4" Rope Black W/PSA Per Inch (Glass)		Y	\$ 1.49 ft
1-00-00888	Gasket, 3/8" Rope White LD Per Inch (Ash Door or Load Door)			\$ 26.00
1-00-00248	Gasket, Hopper			\$ 22.00
3-44-06179	Gasket, Pellet Tailpipe			\$ 9.00
2-00-773862	Glass Clip	Qty 4 req		\$ 3.99
1-10-09109	Hopper Lid W/Hinge			\$ 60.80
3-20-00450	Igniter			\$ 132.80
3-10-724203	Igniter Barb Fitting			\$ 9.00
2-00-724121B	Igniter Mounting Bracket			\$ 6.00
3-31-199110	Latch, Swell/Hopper			\$ 12.50
1-10-08542	Outside Air Vent			\$ 53.00
3-20-00906	Room Sensor		Y	\$ 20.49
3-20-02679C	Rubber Feet, Air Pump			\$ 3.99
1-00-00744	Thermister Probe (ESP Probe)	Pre 008055031	Y	\$ 56.49
3-20-00844		Post 008055031	Y	\$ 49.40
3-20-02680	Wiring Harness			\$ 41.99
Old Feeder				
1-10-06810A	Air Intake Damper			\$ 17.60
1-10-06461	Air Intake Weldment			\$ 30.00
1-10-08037	Slide Plate Assembly			\$ 19.80
1-10-08535	Pusher Arm Assembly			\$ 30.00
3-44-677153	Gasket, EPDM Feeder			\$ 3.99
2-00-677152B	Feed Cover			\$ 9.00
3-50-00465	Auger Assembly		Y	\$ 80.49
3-31-3014	Cam Bearing			\$ 12.50
2-00-04035L	Bearing Flange			\$ 6.00
2-00-01534L	Bracket, Gear Motor			\$ 3.99
3-20-60906	Gear Motor, 4 RPM		Y	\$ 111.99
3-00-00153	Feeder Cam Block			\$ 19.80
1-00-511427	9 mm Silicone Tubing			\$ 39.90
UL Feeder - New Production will be moving to this feeder				
3-20-09302	Pellet Feeder Gear Motor, 6RPM		Y	\$ 164.99
3-31-3014	UL Feeder Cam			\$ 12.50
1-00-511427	9MM Silicone Tube			\$ 39.90
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99
1-10-72222	UL Feeder Air Intake			\$ 30.00
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-724132	Ultra Feeder Weldment			\$ 95.40
1-10-677131W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-00409	Gasket, UL Feeder			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40
3-50-00565	UL Feeder Auger Assembly			\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00

PC-45 Corn Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y-

These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

**Stocked
At
Squier
Lumber**

**SQUIER
LUMBER
2010
PRICING**

PART NUMBER	Description	COMMENTS		
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00