

TL300 Freestanding Wood Stove

IMPORTANT: THIS IS DATED INFORMATION.

Service or replacement parts for your appliance please provide model number and

items. Stock availability is determined by normal

**Stocked
At
Squier
Lumber**

**SQUIER
LUMBER
2010
PRICING**

PART NUMBER	Description	COMMENTS		
1-10-06928P	Rear Air Jacket			\$ 145.60
3-30-2252005013	Hardware - 8.2 Flng 1/4-20 x 1/2" Z	Qty. 12 req.		\$ 3.99
2-00-06922L	Combustion Package Cover			\$ 41.80
3-40-06999	Combustion Package			\$ 253.50
3-44-06949	Combustion Package Base Gasket	Qty. 2 req.		\$ 10.00
3-44-2500202	Interram Gasket	Qty. 2 req.		\$ 6.00
2-00-06943P	Outside Air Plate			\$ 45.60
3-30-1311812513	Hardware - HCS 5/16-18 x 1 1/4	Qty. 6 req.		\$ 1.00
1-10-06946P	Top Air Grill Assembly			\$ 55.10
1-10-06921A	Top Load Door Assembly			\$ 102.00
2-00-40022L	Bottom Lid Hinge	Qty. 2 req.		\$ 6.00
2-00-40021L	Hinge Spacer	Qty. 2 req.		\$ 3.99
3-31-08724	.250 x .375 Dowel Pin	Qty. 2 req.		\$ 3.99
2-00-06926P	Left Side Shield			\$ 45.60
2-00-05223P	Andrion Extensions	Qty. 2 req.		\$ 6.00
2-00-05222	Andiron	Qty. 2 req.		\$ 9.00
3-30-1311807513	Hardware - HCS 5/16-18 x 3/4" Z 5	Qty. 2 req.		\$ 3.99
3-30-02003114	Hardware - USS FW .3125	Qty. 2 req.		\$ 3.99
1-10-06920A	Door Assembly			\$ 298.20
1-10-06915A	Ash Door Assembly			\$ 122.40
2-00-06952B	Bolt on Ash Door Hinge			\$ 10.00
1-10-06938	Ash Pan			\$ 64.60
2-00-06927P	Right Side Shield			\$ 45.60
	Air Slide Assembly			
2-00-06963B	Rod Bracket			\$ 9.00
1-10-06964W	Air Slide Adjuster			\$ 15.40
1-10-06950W	Air Slide Weldment			\$ 12.50
1-00-06902	Kit A (Includes Screws, Steel Sleeve Bushing)			\$ 10.00
1-00-06903	Kit B (Includes Screws, Steel Sleeve Bushing, Latch Adjuster Plate, Reverse Lock Nut).			\$ 17.60
3-40-06932	Load Door Glass			\$ 116.00
1-00-2312	Glass Gasket		Y	\$ 1.49 ft
1-00-00888	Load Door Gasket			\$ 26.00
1-00-10000	Ash Door Gasket			\$ 12.50
Firebox				
1-10-249106	Damper Frame Assembly (Includes Damper)			\$ 172.80
2-00-249153	Rear Brick Clip	Qty. 2 req.		\$ 10.00
1-10-249117A	Left Inside Plate Assembly			\$ 40.00
3-40-00101	Logo Brick			\$ 60.80
3-40-00103	Inlet Brick Left			\$ 95.40
2-00-06945B	Side Brick Bracket	Qty. 2 req.		\$ 6.00
3-40-86125	Fire Brick 6" x 12"	Qty. 4 req.		\$ 17.60
3-40-06944	Brick Insulation	Qty. 2 req.		\$ 12.50
2-00-06925B	Grate			\$ 43.70
3-40-00104	Inlet Brick Right			\$ 79.20

TL300 Freestanding Wood Stove

IMPORTANT: THIS IS DATED INFORMATION.

For service or replacement parts for your appliance please provide model number and

part numbers. Stock availability is determined by normal

PART NUMBER			Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
1-10-249118A			Right Inside Plate Assembly			\$ 40.00
3-44-06951			Shoe Brick Gasket			\$ 15.00
3-40-00100			Shoe Brick			\$ 90.00
1-00-06900			Hardware Package (Includes Screws, Centerlock Nuts)			\$ 12.50
Damper Arm Assembly						
3-31-500015			Push-On Cap Lift Arm			\$ 3.99
3-40-06956			Wooden Knob			\$ 10.00
1-10-06937W			Damper Linkage Arm Weldment (Includes knob & cap)			\$ 79.20
2-00-06924L			Damper Pivot Gear			\$ 9.00
2-00-06923L			Damper Idler Gear			\$ 9.00
1-10-06916W			Damper Arm Gear Weldment			\$ 51.30
1-10-06918W			Damper Shaft Cover Weldment			\$ 36.00
1-10-249146			Damper Linkage Weldment			\$ 32.00
1-00-06901			Hardware Package (Includes Drive Arm Washer, Pusher Block Bushing, Wave Washer, Screws)			\$ 12.50