

# XXV Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.  
 service or replacement parts for your appliance please provide model number and

items. Stock availability is determined by normal

**Stocked  
At  
Squier  
Lumber**

**SQUIER  
LUMBER  
2010  
PRICING**

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
3-00-247237	Pellet Tailpipe Cast		Y	\$ 16.39
3-44-06179	Pellet Tailpipe Gasket		Y	\$ 9.49
1-10-677085A	Right Feeder Shield			\$ 40.00
1-10-677084A	Left Feeder Shield			\$ 30.00
1-10-677800A	Hopper Assembly	Pre 12826		\$ 300.00
1-10-677049A		12826 thru 008203932		\$ 177.60
1-10-677190A		Post 12826		\$ 182.40
3-20-232108	Hopper Switch 48"	Post 008203932		\$ 38.00
3-20-6866	Differential Switch		Y	\$ 16.29
1-10-677153A	Feeder Assembly	Pre 12826		\$ 445.20
1-10-677189A		Post 12826		\$ 336.00
3-44-00409	Pellet Burn Pot Gasket		Y	\$ 4.99
3-21-08639	Combustion Blower		Y	\$ 108.99
3-44-677037	Hopper Insulation			\$ 30.00
3-40-247100	Hopper Lid			\$ 45.60
2-00-06694	Hinge			\$ 24.00
3-43-02000	Hopper Knob	Gold		\$ 6.00
3-43-02000-8		Brushed Nickel		\$ 15.40
2-00-06695L	Hopper Plate	Qty. 2 Req.		\$ 3.99
2-00-06696	Hopper Lid Latch	Male		\$ 6.00
2-00-06697		Female		\$ 6.00
4-00-677057	Plain Top			\$ 128.00
4-00-677055	Left Side			\$ 144.00
3-31-12302	Leveler Feet	Qty. 4 req.		\$ 9.00
1-00-677300	Airwash Reducer			\$ 15.40
2-00-677096B	Ash Door Stop			\$ 22.00
2-00-677025B	Ash Door Gasket Retainer			\$ 26.00
4-00-677058	Ashlip			\$ 47.50
1-10-677044	Ash Pan			\$ 49.40
1-10-677026A	Ash Door Weldment			\$ 53.20
3-31-677070	Cable Lanyard			\$ 6.00
1-10-677099A	Load Door Assembly			\$ 200.00
2-00-677022S	Letters			\$ 40.00
1-10-00675	Burn Pot		Y	\$ 113.19
3-00-03000	Flame Guide		Y	\$ 24.49
3-44-724114	Ceramic Insert Gasket			\$ 22.00
2-00-677006L	Distribution Blower Mount Plate			\$ 22.00
3-21-29045	Distribution Blower		Y	\$ 132.99
3-31-2181	Extension Spring			\$ 9.00
3-00-674047	Hinge Plate	Qty. 2 req.		\$ 12.50
4-00-677056	Right Side			\$ 144.00
2-00-677039B	Air jacket Filler Plate			\$ 15.00
2-00-677035B	Air Jacket			\$ 41.80
2-00-677038B	Hopper Heat Shield			\$ 38.00

# XXV Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.  
service or replacement parts for your appliance please provide model number and

items. Stock availability is determined by normal

**Stocked  
At  
Squier  
Lumber**

**SQUIER  
LUMBER  
2010  
PRICING**

PART NUMBER	Description	COMMENTS		
2-00-677041B	Distribution Blower Heat Shield			\$ 19.80
2-00-677040B	Combustion Box Heat Shield			\$ 22.00
2-00-677087L	Rear Shield Spacer			\$ 12.50
2-00-677086L	Rear Shield Retainer			\$ 3.99
3-44-677042	Combustion Assembly Insulation			\$ 15.40
3-20-502221	5" Double Blade		Y	\$ 13.99
1-00-05886	Control Board		Y	\$ 169.99
3-40-677000	Glass Door		Y	\$ 149.99
1-00-1186258229	Glass Rope			\$ 10.00
3-20-677200	Ignitor		Y	\$ 91.49
2-00-06620B	Ignitor Cradle			\$ 3.99
2-00-06621B	Ignitor Holder		Y	\$ 9.99
2-00-06633L	Ignitor Flat Bottom			\$ 3.99
3-30-02002514	USS FW 1/4" Z	Qty. 4 req.		\$ 3.99
3-30-03008	SQ Washer 8PBevel M8x22x22	Qty. 4 req.		\$ 3.99
3-30-03031	.3125 External Tooth Lock Washer	Qty. 4 req.		\$ 3.99
3-30-1102405036	HWH TCS 10-24 x 1/2" Black	Qty. 8 req.		\$ 3.99
3-30-1252006216	HWH TCS .25-20 x .625 Type 23	Qty. 3 req.		\$ 3.99
3-30-1252010013	HCS .25-20 x 1 Z 5	Qty. 2 req.		\$ 3.99
3-30-1371605013	HCS .375 16 x .500 Z 5			\$ 3.99
3-30-2252003813	8.2 Flng 1/4-20 x 3/8" Z	Qty. 2 req.		\$ 3.99
3-30-2252006213	8.2 Flng .25-20 x .625 Z	Qty. 6 req.		\$ 3.99
3-30-2925201502	SSS CP .25-20 x 1.5	Qty. 4 req.		\$ 3.99
3-30-3025202252	SHCS 1/4-20 x 2-1/4"			\$ 3.99
3-30-510807516	HWH TEKS #8 x 3/4"	Qty. 9 req.		\$ 3.99
3-30-80311813	FHN 5/16-18 Z5	Qty. 4 req.		\$ 3.99
3-30-80311824	FHN .3125-18 Z 8 Plain	Qty. 4 req.		\$ 3.99
3-30-8725201	Flange Nut 1/4-20	Qty. 4 req.		\$ 3.99
3-31-782108	1/4-20 Wing Screw with Collar	Qty. 3 req.		\$ 3.99
3-50-05230	Steel Sleeve Bushing 1/2" OD x 3/4"			\$ 3.99
3-50-05232	Steel Sleeve Bushing .5 OD x .375			\$ 3.99
<b>Old Feeder</b>				
1-10-677016W	Air Intake Weldment			\$ 40.00
1-10-677150	Feeder Weldment		Y	\$ 126.40
1-10-08037	Slide Plate Assembly		Y	\$ 32.99
1-10-01530	Pusher Arm Assembly			\$ 28.00
3-44-677153	Gasket, EPDM Feeder Cover		Y	\$ 1.99
2-00-677152B	Feed Cover			\$ 9.00
3-20-08752	Gear Motor, 4 RPM		Y	\$ 96.49
1-10-677005	Bracket, Gear Motor			\$ 17.60
3-31-00075	Tensioner			\$ 6.00
3-50-08550	Large Sprocket With hub		Y	\$ 24.49
3-50-06667	Drive Chain 60 Pin			\$ 19.80
3-50-06626	Large Sprocket Without hub		Y	\$ 18.29
3-00-00153	Cast Cam Block			\$ 19.80

# XXV Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.  
 service or replacement parts for your appliance please provide model number and

items. Stock availability is determined by normal

			Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
PART NUMBER	Description	COMMENTS		
3-31-3014	Cam Bearing			\$ 12.50
2-00-04035L	Bearing Flange			\$ 6.00
3-50-00465	Auger Assembly		Y	\$ 80.49
1-10-06810A	Air Intake Damper Assembly			\$ 17.60
<b>UL Feeder - Beginning Serial Number 12826 thru 12939 and from 008200001 onward</b>				
3-20-00677	Pellet Feeder Gear Motor, 4 RPM		Y	\$ 96.49
3-31-3014	UL Feeder Cam Bearing			\$ 12.50
1-00-511427	9MM Silicone Tube			\$ 39.90
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99
1-10-677183	UL Feeder Air Intake			\$ 43.70
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-724132	Ultra Feeder Weldment			\$ 95.40
1-10-677131W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-677155	Gasket, UL Feeder Cover			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40
3-50-00565	UL Feeder Auger Assembly		Y	\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00
3-00-677154	UL Feeder Cam Block			\$ 19.80