

# P38+ Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

**Stocked At Squier Lumber**

**SQUIER LUMBER 2010**

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	PRICING
1-10-08517	Hopper Assembly	Pre 008080620		\$ 195.00
1-10-7738102A		008080620 Thru 008084166		\$ 180.80
1-10-09536A		Post 008084166		\$ 225.00
3-20-232108	Hopper Switch 48"	Post 008484166	Y	\$ 34.99
1-10-09525	Feeder Assembly	Pre 008080620		\$ 396.20
1-10-09535A		Post 008080620		\$ 368.20
3-00-247237	Flue Tail Pipe		Y	\$ 16.39
2-00-773852P	Auger Motor Cover			\$ 24.00
2-00-773815P	Auger Motor Shield			\$ 30.00
3-20-6866	Differential Switch		Y	\$ 16.29
3-21-22647	Distribution Blower		Y	\$ 142.99
3-21-08639	Combustion Motor		Y	\$ 108.99
2-00-773828-1P	Rear Cover Left			\$ 22.00
2-00-773828-2P	Rear Cover Right			\$ 22.00
1-10-08516S	Combustion Intake Weldment			\$ 22.00
1-10-08533S	Retainer Assembly			\$ 15.00
1-10-08508	Ash Pan	Pre 10327		\$ 144.00
1-10-773873		10327 to 008080620		\$ 57.00
1-10-7738108A		Post 008080620		\$ 62.70
1-10-773871	Ash Door Assembly	Pre 008080620		\$ 91.80
1-10-7738106A		Post 008080620		\$ 99.00
2-00-06952B	Bolt on Hinge Weldment			\$ 10.00
4-00-06800P	Cast Door Frame			\$ 97.20
3-40-950133125	Glass Panel			\$ 58.90
1-00-08704	Door Handle Assembly (Contains: Paw Bolt, Wooden Handle, Washers and Screws.)	Pre 10327	Y	\$ 40.49
1-00-453001		Post 10327		\$ 55.10
3-40-00122	Wooden Handle, Load Door	Pre 10327		\$ 6.00
3-40-00247		Post 10327		\$ 6.00
1-10-08514	Burn Pot Weldment		Y	\$ 108.99
3-00-08534	Flame Guide		Y	\$ 24.49
2-00-06623	Clean Out Cover			\$ 6.00
3-31-782108	Thumb Screw	Qty 2 req		\$ 3.99
3-40-900450125	Fire Brick 4-1/2 x 9 x 1-1/4"	Qty 1 req		\$ 6.00
2-00-773854B	Hopper Heat Shield			\$ 15.40
2-00-773853	Feeder Cover			\$ 9.00
1-00-03769	Circuit Board		Y	\$ 139.99
1-10-08327	Circuit Board Plate		Y	\$ 23.64
3-31-605	Knob, Contol Board/D-Shaft	Qty 3 req	Y	\$ 3.99
3-31-015	Control Knob Shaft, D-Shaped	Qty 3 req	Y	\$ 3.99
<b>Accessories</b>				
2-00-773850	Arrow Burn Pot Scraper			\$ 9.00
3-20-502221	Fan Blade, 5" Double Paddle (Combustion Blower)		Y	\$ 15.29
3-20-49447	Fuse, 6 Amp			\$ 3.99
1-00-2312	Gasket, 1/4" Rope Black W/PSA Per Inch (Glass)		Y	\$ 1.49 ft
1-00-00888	Gasket, 3/8" Rope White LD Per Inch (Ash Door or Load Door)			\$ 26.00
3-44-00409	Gasket, Burn Pot		Y	\$ 4.99
1-00-00248	Gasket, Hopper		Y	\$ 1.19 ft

# P38+ Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

**Stocked  
At  
Squier  
Lumber**

**SQUIER  
LUMBER  
2010  
PRICING**

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
3-44-677185	Gasket, Hopper Throat			\$ 19.80
3-44-06179	Gasket, Pellet Tailpipe		Y	\$ 9.49
2-00-773862	Glass Clip	Qty. 4 req.		\$ 3.99
3-30-3110240382	Glass clip Screws	Qty. 4 req.		\$ 3.99
1-10-08518	Hopper Lid W/Hinge			\$ 40.00
3-31-199110	Latch, Swell/Hopper			\$ 12.50
3-40-6618	Muffler		Y	\$ 10.99
3-40-1818	Muffler Fitting		Y	\$ 7.27
1-10-08542	Outside Air Vent		Y	\$ 53.00
3-20-29685	Power Cord			\$ 12.50
1-00-00744	Thermister Probe (ESP Probe)			\$ 53.20
3-20-12080	Thermostat		Y	\$ 70.40
3-20-773868	Wiring Harness			\$ 28.00
3-90-08422	Owners Manual			\$ -
3-42-1990	<b>Touch Up Spray Paint (12 ounce)</b>	Black	Y	\$ 11.99
3-42-6201		Charcoal	Y	\$ 11.99
3-42-6198		Forest Green	Y	\$ 11.99
3-42-6230		Goldenfire	Y	\$ 11.99
3-42-6196		Metalic blue	Y	\$ 11.99
3-42-6319		Mojave Red	Y	\$ 11.99
<b>Old Feeder</b>				
1-10-06810A	Air Intake Damper Assembly			\$ 17.60
1-10-773843	Air Intake Weldment			\$ 24.00
1-10-677150	Feeder Weldment		Y	\$ 278.99
1-10-08037	Slide Plate Assembly		Y	\$ 32.99
1-10-773890	Pusher Arm Assembly			\$ 28.00
3-44-677153	Gasket, EPDM Feeder Cover			\$ 3.99
2-00-677152B	Feed Cover			\$ 9.00
3-50-00465	Auger Assembly		Y	\$ 80.49
3-31-3014	Cam Bearing			\$ 12.50
2-00-04035L	Bearing Flange			\$ 6.00
2-00-01534L	Bracket, Gear Motor			\$ 3.99
3-20-60906	Gear Motor, 4 RPM		Y	\$ 111.99
3-00-00153	Cast Cam Block			\$ 19.80
<b>UL Feeder - Beginning Serial Number 008080620</b>				
3-20-60906	Pellet Feeder Gear Motor, 4 RPM		Y	\$ 111.99
3-31-3014	UL Feeder Cam Bearing			\$ 12.50
1-00-511427	9MM Silicone Tube			\$ 39.90
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99
1-10-72222	UL Feeder Air Intake			\$ 30.00
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-724132	Ultra Feeder Weldment			\$ 95.40
1-10-677131W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-677155	Gasket, UL Feeder Cover			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40

# P38+ Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
3-50-00565	UL Feeder Auger Assembly		Y	\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00
3-00-677154	UL Feeder Cam Block			\$ 19.80