

P68 Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION. When requesting service or replacement parts for your appliance please provide model number and serial number. (Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked at Squier Lumber	SQUIER LUMBER 2010 PRICING
1-10-06709	Hopper Assembly	Pre 008280309		\$ 234.00
1-10-06818A		008280309 thru 008284286		\$ 204.00
1-10-07907S		Post 008274286		\$ 225.00
3-20-232108	Hopper Switch	Post 008284286	Y	\$ 34.99
1-10-07806	Feeder Assembly	Pre 008280309		\$ 414.40
1-10-07906A		Post 008280309		\$ 308.00
3-00-247237	Flue Tail Pipe		Y	\$ 16.39
2-00-06470P	Auger Motor Cover			\$ 28.00
2-00-06467P	Auger Motor Shield			\$ 24.00
3-20-6866	Differential Switch		Y	\$ 16.29
3-21-22647	Distribution Blower		Y	\$ 142.99
3-21-08639	Combustion Motor		Y	\$ 108.99
2-00-06468-1P	Rear Cover Left			\$ 22.00
2-00-06468-2P	Rear Cover Right			\$ 22.00
1-00-06713	Door Latch Assembly			\$ 15.40
	Contains: Latch Adjustment, SHCS(1/4-20 X 1), Nut (FHN 1/4 X 20Z5), Jam Nut (HX Jam 1/4-20Z) Steel Bushing,			
1-10-08516S	Comb Intake Weldment			\$ 22.00
1-10-08533S	Retainer Assembly			\$ 15.00
1-10-05800	Ash Pan			\$ 62.70
1-10-06724S	Ash Door Assembly			\$ 96.90
2-00-06952B	Bolt on Hinge			\$ 10.00
3-00-06718P	Cast Door Frame			\$ 115.60
3-40-00688	Glass Panel			\$ 122.40
1-00-249119	Door Handle Assembly			\$ 43.70
	Contains: Handle, 6 mm Washer, SHCS, handle, Dowel, Plunger, SSS, B			
3-31-5500	Ball Plunger, 5/16 X 1/2 Black		Y	\$ 3.19
3-00-249119	Front Door Latch			\$ 28.00
3-40-00123	Wooden Handle , Load Door			\$ 9.00
1-10-06723	Burn Pot Weldment		Y	\$ 140.99
3-00-03000	Flame Guide			\$ 24.49
2-00-06623	Clean Out Cover			\$ 6.00
3-31-782108	Thumb Screw	Qty 2 req		\$ 3.99
3-40-900450125	Fire Brick 4-1/2 x 9 x 1-1/4"	Qty 3 req		\$ 6.00
2-00-06715B	Hopper Heat Shield			\$ 19.80
2-00-773826L	Feeder Opening Cover			\$ 6.00
1-00-05886	Circuit Board		Y	\$ 148.99
1-10-08327	Circuit Board Plate-Studded w/label			\$ 26.00
3-31-605	Knob, Contol Board/D-Shaft	Qty 3 req	Y	\$ 3.99
3-31-015	Control Knob Shaft, D- Shaped	Qty 3 req	Y	\$ 3.99
Accessories				
2-00-773850	Arrow Burn Pot Scraper			\$ 9.00
	Cradle Assembly			
2-00-06621B	Igniter Holder			\$ 10.00
2-00-06620B	Igniter Cradle			\$ 3.99
2-00-06633L	Igniter Flat Bottom			\$ 3.99

P68 Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION. When requesting service or replacement parts for your appliance please provide model number and serial number. (Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked at Squier Lumber	SQUIER LUMBER 2010 PRICING
3-20-502221	Fan Blade, 5" Double Paddle (Combustion Blower)		Y	\$ 15.29
3-20-49447	Fuse, 6 Amp			\$ 3.99
1-00-2312	Gasket, 1/4" Rope Black W/PSA Per Inch (Glass)		Y	\$ 1.49 ft
1-00-00888	Gasket, 3/8" Rope White LD Per Inch (Ash or Load Door)			\$ 26.00
3-44-00409	Gasket, Burn Pot			\$ 3.99
3-44-724114	Gasket, Overfire Air Burn Pot			\$ 22.00
1-00-00248	Gasket, Hopper			\$ 22.00
N/A	Gasket, Hopper Throat	Pre 008280309		
3-44-677185		Post 008280309		\$ 19.80
3-44-06179	Gasket, Pellet Tailpipe		Y	\$ 9.49
2-00-249140	Glass Clip	Qty 4 req		\$ 3.99
1-10-09109	Hopper Lid and Hinge			\$ 60.80
3-20-677200	Igniter		Y	\$ 91.49
2-00-06714	Latch Ball Spring Bracket			\$ 3.99
3-31-199110	Latch, Swell/Hopper			\$ 12.50
3-40-6618	Muffler			\$ 15.00
3-40-1818	Muffler Fitting		Y	\$ 10.00
1-10-08542	Outside Air Vent		Y	\$ 53.00
3-20-00906	Room Sensor		Y	\$ 20.49
1-00-00744	Thermister Probe (ESP Probe)	Pre 008280309	Y	\$ 56.49
3-20-00844		Post 008280309	Y	\$ 49.40
3-20-00607	Thermostat Extension			\$ 15.00
3-20-08727	Wiring Harness			\$ 47.50
3-42-1990	Touch Up Spray Paint (12 Ounce)	Black	Y	\$ 11.99
3-42-6196		Metalic blue	Y	\$ 11.99
3-42-6198		Forest Green	Y	\$ 11.99
3-42-6201		Charcoal	Y	\$ 11.99
3-42-6230		Golden Fire	Y	\$ 11.99
3-42-6319		Mojave Red	Y	\$ 11.99
Old Feeder				
1-10-06810A	Air Intake Damper Assembly			\$ 17.60
1-10-06461	Air Intake Weldment			\$ 30.00
1-10-677150	Feeder Weldment		Y	\$ 278.99
1-10-08037	Slide Plate Assembly		Y	\$ 32.99
1-10-06719	Pusher Arm Assembly			\$ 30.00
3-44-677153	Gasket, EPDM Feeder Cover		Y	\$ 1.99
2-00-677152B	Feed Cover			\$ 9.00
3-50-00465	Auger Assembly		Y	\$ 80.49
3-31-3014	Cam Bearing			\$ 12.50
2-00-04035L	Bearing Flange			\$ 6.00
2-00-01534L	Bracket, Gear Motor			\$ 3.99
3-20-60906	Gear Motor, 4 RPM		Y	\$ 111.99
3-00-00153	Cast Cam Block			\$ 19.80
UL Feeder - Beginning Serial Number 008280309				
3-20-09302	Pellet Feeder Gear Motor, 6RPM		Y	\$ 164.99
3-31-3014	UL Feeder Cam			\$ 12.50
1-00-511427	9MM Silicone Tube		Y	\$ 39.90

P68 Pellet Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked at Squier Lumber	SQUIER LUMBER 2010 PRICING
1-10-06810A	Pellet Air Intake Assembly			\$ 17.60
3-44-72224	Gasket Feeder Air Intake			\$ 3.99
1-10-72222	UL Feeder Air Intake			\$ 30.00
3-44-677160	Gasket Ultra Air Intake			\$ 3.99
1-10-724132	Ultra Feeder Weldment			\$ 95.40
1-10-677131W	UL Feeder Pusher Arm			\$ 30.00
2-00-677138B	Fines Deflector			\$ 6.00
3-44-677155	Gasket, UL Feeder Cover			\$ 3.99
2-00-677122L	UL Feeder Cover Short			\$ 6.00
1-10-677121A	Slide Plate Assembly			\$ 15.40
3-50-00565	UL Feeder Auger Assembly		Y	\$ 86.40
2-00-04035L	Pellet Feeder Bearing Retainer			\$ 6.00
2-00-247406L	UL Feeder Gear Motor Bracket			\$ 6.00
3-00-677154	UL Feeder Cam Block			\$ 19.80