

TL200 Exception Wood Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

Stocked At Squier Lumber

SQUIER LUMBER 2010 PRICING

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING
1-10-05144A	Top load door - no gasket plate			\$ 112.20
1-10-08075	Damper pivot arm weldment			\$ 38.00
1-10-08127	Top lift arm weldment			\$ 15.40
1-10-08074	Damper linkage arm weldment w/knob			\$ 66.50
3-40-05228	Wooden knob for damper arm			\$ 10.00
2-00-05204	Left side shield			\$ 64.60
2-00-05226L	Damper clip	Qty. 2 Req.		\$ 6.00
1-10-08077	Damper weldment			\$ 45.60
3-40-05171	Ceramic fiber afterburner			\$ 126.40
1-10-08057	Cast damper frame w/gasket and clips			\$ 100.30
1-10-08058	Left side plate assembly			\$ 47.50
1-10-08059	Right side plate assembly			\$ 25.00
1-10-08200	Afterburner hood weldment			\$ 223.50
2-00-07071-1	After Burner Glass Clip - left			\$ 9.00
3-40-05180	Afterburner glass			\$ 10.00
2-00-07071-2	Afterburner glass clip - right			\$ 9.00
1-10-08111	Ramp assembly			\$ 45.60
3-40-00122	Wooden handle			\$ 6.00
3-40-00121	Brass elbow			\$ 17.60
3-40-05174	Glass rect 12-7/16" X 17-5/8"			\$ 152.00
2-00-05202	Glass clips TI/dvc/win	Qty. 4 Req.		\$ 6.00
2-00-05147	Steel grate	Qty. 2 Req.		\$ 22.00
3-40-900450125	Standard Brick 9" X 4-1/2" x 1-1/4"	Qty. 4 Req.		\$ 6.00
2-00-05222	Andirons	Qty. 2 Req.		\$ 9.00
2-00-05205	Right side shield			\$ 66.50
3-30-1311830014	Afterburner bolts			\$ 3.99
2-00-08611	Afterburner glass replacement - steel			\$ 6.00
2-00-05223P	Andiron extension			\$ 6.00
1-10-05148	Ash pan			\$ 64.60
1-00-08125-1	Black classic door kit			\$ 223.00
1-00-08118	Blower - w/ mounting plate			\$ 199.00
3-21-50757	Blower - w/o mounting plate			\$ 238.50
2-00-05218P	Blower mount			\$ 22.00
2-00-06952B	Bolt on ash door hinge			\$ 10.00
2-00-40022L	Bottom lid hinge (top load door - 2 per)			\$ 6.00
3-40-05185	Brick insulation			\$ 22.00
2-00-05265	Cooking grill handle			\$ 10.00
3-40-727336	Cozy screen			\$ 59.00
1-10-08107	Damper arm weld. (Goes through stove body) Win/tl200			\$ 15.40
3-30-80252013	Damper clip nut - fhn 1/4-20 z 5			\$ 3.99
1-10-40020	Gasket plate - top load door w/gasket			\$ 58.90
1-10-05165	Gold door (frame only) TI/dvc/win			\$ 193.60
1-00-08125-4	Gold door kit			\$ 431.00
1-00-08176	Handle assembly			\$ 40.00
1-00-08120	Outside air option			\$ 38.00
3-31-375012	Push on cap for wood knob			\$ 3.99

TL200 Exception Wood Stove

IMPORTANT: THIS IS DATED INFORMATION.

When requesting service or replacement parts for your appliance please provide model number and serial number.

(Y- These parts are generally stocked items. Stock availability is determined by normal seasonal usage and may vary)

PART NUMBER	Description	COMMENTS	Stocked At Squier Lumber	SQUIER LUMBER 2010 PRICING	
1-00-08119	Set of cut brick			\$ 16.00	
1-00-08617	Tile frame assembly 12 X 6 - gold			\$ 33.00	
1-00-08122	Top air grill			\$ 61.00	
Tile Packs					
3-43-120601	Ceramic Tile 12 x 6 (1 pc)	Pheasants		\$ 60.00	
3-43-120602		Deer		\$ 60.00	
3-43-120603		Mallards		\$ 60.00	
3-43-120604		Old Mill		\$ 60.00	
3-43-120605		Cottage		\$ 60.00	
3-43-120606		Eagle		\$ 60.00	
3-43-120607		Bridge		\$ 60.00	
3-43-120608		Bear		\$ 60.00	
3-43-120609		Lighthouse		\$ 60.00	
3-43-120610		Trout		\$ 60.00	
1-00-06732-2		Brushed Stainless Steel Plate	Deer		\$ 60.00
3-43-06731-11		Slate Tile 12 x 6 (1 pc)	Floral		\$ 60.00
3-43-06731-12	Horse Riders			\$ 60.00	
3-43-06731-2	Deer			\$ 60.00	
3-43-06731-9	Lighthouse			\$ 60.00	